

Display PM Notification: Maintenance Request

Notification 935680125 UM repair leaks on the Trimer
Notific. Status NOCO CRTD

Creation Availability Completion Location Dates Maintenance plan Causes Cu

Reference object

Functional loc. UTEL-CAT-AGEI-C-B-58235102 BUILDING 5C
Equipment
Assembly

Start/End Dates

Required Start 03/10/2016 19:41:06 Priority VeryHigh (Immediate)
Required End 03/11/2016 19:41:06 ☐ Breakdown
Revision UTEL

Responsibilities


Planner group PLN / UTEL Maint Planner
Main WorkCtr MECH / UTEL Mechanical Craftsperson
Person Responsl
Reported by STOCKDJ Notif.date 03/10/2016 18:51:47



Subject

Description repair leaks on the Trimer

03/10/2016 19:41:06 EST Douglas Stock (STOCKDJ) Phone +1 440 329 2563
The Trimer is still leaking from the flange. Please have it inspected
and repaired further. Thanks!
03/11/2016 06:34:37 EST GREGORY MENZ (MENZGR) Phone +1 440 329 2538
Duplicate.

Display PM Notification: Maintenance Request



Notification 
 Notific. Status 

Reference object


Functional loc. BUILDING 5C
 Equipment
 Assembly



Start/End Dates

Required Start Priority
 Required End ☐ Breakdown
 Revision

Responsibilities

Planner group / Maint Planner
 Main WorkCtr / Mechanical Craftsperson
 Person Responsi
 Reported by Notif.date 

Subject

Description

03/02/2016 03:53:03 EST Douglas Stock (STOCKDJ) Phone +1 440 329 2563
 Please repair the leak on the stage 1 tower of the Trimer in bldg 5C.
 Solution was leaking on the south side of the tower at the seam a few
 feet below the recirculation line inlet to the nozzle (at the level of
 the second mezzanine). A loud popping sound was heard before the caustic
 water solution started to flow out.
 03/02/2016 10:26:29 EST M. WILLBOND (WILLBOM) Phone 440-329-2503 2503

